

# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-043	Smoke	9/5/2008	ADS/TM	S15GG1025MH	Dry	Yes	635.71



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-043	Smoke	9/5/2008	ADS/TM	S15GG1025MH	Dry	Yes	635.71

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13GG1011G1	S13GG1011MH	S15GG1025MH	241.5544	8
S15GG1025G1	S15GG1025MH	S15GG1011MH	140.6404	8
S15GG1011G1	S15GG1011MH	S15GG1020MH	253.5190	8

### Observations & Photos

**Obs\_ID** S1028-043-OB01

**Address** 2619 Park Heights Terr


**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S15GG1025MH

**Comments** Smoke from cleanout in back yard. 2619 Park Heights Terr



**Picture** \S1028-043-OB01-P01.jpg

**Comments** Back of house, 2619 Park Heights Terr

**Obs\_ID** S1028-043-OB02

**Address** 2631 Park Heights Terr

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S13GG1011MH

**Comments** Smoke from cleanout in back yard. 2631 Park Heights Terr



**Picture** \S1028-043-OB02-P01.jpg

**Comments** Back of house, 2631 Park Heights Terr